EARLE H. BARLOW
120 Tremont Street, Boston, Mass.

TO HENRY D MORSE

DESIGNS

Henry D. Morse
Boston
Mass

Sam'l T. Crosby 1885

Chas. M. Foss. 1886.
to 120 Tremont St.
Boston
Mass

Charles M. Foss
Successor to
Diamond and Watch Case Repairing
120 Tremont Street
Phillips Building
Rooms 223 and 224

Earle H. Barlow
120 TREMONT STREET
BOSTON, MASS.

To Successor - To —
Charles W. Foss
1940

9894



Henry D. Morse
Boston
Mass

Sam'l T. Crost

Chas. M. H
to 120 Tre

Mass.

Charles O. Pe
Successor to
Oliver & Pe
Diamonds and Watches
120 Tremont Street
Phillips Building
Rooms 233 and 239
Boston.

Earle H. Barlow
120 TREMONT STREET
BOSTON, MASS.

To SUCCESSOR - TO -
CHARLES W. FOSS
1940



7685













No. 14

No. 15.

No. 16.

No. 17.































A









Y











No 1

2







FATHER

Cy no 119











Plain onyx locket 1 Letter ff= to Bx=
" " " 3 " af= to 12x=
Outside pearls or diamonds Extra



Crosby & Foss
421 Washington St

























Souvenir

A



B.































No. 1.



Minute Length Hand
Hour Length "
Second Length "

Garnet



no.4.





No. 2



Charles W. Foss
120 Tremont Street, Boston, Mass.

To Henry D. Monge
His Designs
See Inside Cover